

EXISTING BRIDGE CONDITIONS



A3200 - Rt. J - Cole Co
Looking South down station
10-5-15




A3200 - Rt. J - Cole Co
Back wall between G4 and G5
10-5-15



A3200 - Rt. J - Cole Co
Girder 4 and 5 bearings at
End Bent 3
10-5-15



A3200 - Rt. J - Cole Co
Falswork Span 1, full depth
repair between Girders
4 and 5
10-5-15



A3200 - Rt. J - Cole Co
Overhang West side of
Bridge (typical) slab drains
10-5-15



Cole A3200 08/24/16
RT J S over US 50
North Abutment